

AAKAR CONSULTANT

DATE: -22-07-25

STABILITY CERTIFICATE

This is to certify that the building of SHANTI ASIATIC SCHOOL AT - Kheda Block/S-NO-354,355

Which is issued as a School Building has been visited by me and found that the building is ground floor, first floor and second floor with good structure with good compound wall around the school. The School Structure is good condition. The structure with 2.no R.C.C. stair. 230 Thick Bricks Masonry wall R.C.C beams and smooth plaster.

Looking to the structure of said building as per by knowledge and Experience that it is a safe and out of any danger up to date.

I recommended this building to be used for school purpose.

The building structure should be inspected by competent structure engineer periodically every one or two year. This building has not been designed or supervised or executed by our firm of me.

Thanking you

FOR AAKAR CONSULTANT



JAYMIN DESAI

**13, LAXMIKUNJ SOCI,
NADIAD.**

NADA - NADIAD

LICENCE No.: 1015 SE 02052902019

Jaymin Desai

13,LAXMIKUNG SOCIETY B/H SHITAL TALKIES NADIAD -387001 Ph- 98240 30308